






Xerox<sup>®</sup> Replacement  
Cartridges  
Quick Reference Guide

# Color—HP Printer replacement toner supplies

Machine Type*	Xerox Part Number	Equivalent OEM Part Number	For Use In	OEM Stated Yield	Xerox Stated Yield
LJ4600**	6R941	C9720A – Black	HP Color LaserJet 4600, 4600n, 4600dn, 4600dtn, 4600hdn, 4650, 4650n, 4650dn, 4650dtn, 4650hdn	9,000‡	9,000‡
LJ4600**	6R942	C9721A – Cyan	HP Color LaserJet 4600, 4600n, 4600dn, 4600dtn, 4600hdn, 4650, 4650n, 4650dn, 4650dtn, 4650hdn	8,000‡	8,000‡
LJ4600**	6R943	C9722A – Yellow	HP Color LaserJet 4600, 4600n, 4600dn, 4600dtn, 4600hdn, 4650, 4650n, 4650dn, 4650dtn, 4650hdn	8,000‡	8,000‡
LJ4600**	6R944	C9723A – Magenta	HP Color LaserJet 4600, 4600n, 4600dn, 4600dtn, 4600hdn, 4650, 4650n, 4650dn, 4650dtn, 4650hdn	8,000‡	8,000‡
LJ2500/LJ2800**	6R1285	C9700A/Q3960A Black	HP Color LaserJet 1500, 2500, 2550, 2800 Series	5,000‡	5,000‡
LJ2500/LJ2800**	6R1286	C9701A/Q3961A Cyan	HP Color LaserJet 1500, 2500, 2550, 2800 Series	4,000‡	4,000‡
LJ2500/LJ2800**	6R1287	C9702A/Q3962A Yellow	HP Color LaserJet 1500, 2500, 2550, 2800 Series	4,000‡	4,000‡
LJ2500/LJ2800**	6R1288	C9703A/Q3963A Magenta	HP Color LaserJet 1500, 2500, 2550, 2800 Series	4,000‡	4,000‡
LJ3500/LJ3550 LJ3700**	6R1289	Q2670A – Black	HP Color LaserJet 3500 Series, 3550 Series, 3700 Series	6,000‡	6,000‡
LJ3500/LJ3550**	6R1290	Q2671A – Cyan	HP Color LaserJet 3500 Series, 3550 Series	4,000‡	4,000‡
LJ3500/LJ3550**	6R1291	Q2672A – Yellow	HP Color LaserJet 3500 Series, 3550 Series	4,000‡	4,000‡
LJ3500/LJ3550**	6R1292	Q2673A – Magenta	HP Color LaserJet 3500 Series, 3550 Series	4,000‡	4,000‡
LJ3700**	6R1293	Q2681A – Cyan	HP Color LaserJet 3700 Series	6,000‡	6,000‡
LJ3700**	6R1294	Q2682A – Yellow	HP Color LaserJet 3700 Series	6,000‡	6,000‡
LJ3700**	6R1295	Q2683A – Magenta	HP Color LaserJet 3700 Series	6,000‡	6,000‡
LJ5500/LJ5550**	6R1313	C9730A – Black	HP Color LaserJet 5500 Series, 5550 Series	13,000‡	13,000‡
LJ5500/LJ5550**	6R1314	C9731A – Cyan	HP Color LaserJet 5500 Series, 5550 Series	12,000‡	12,000‡
LJ5500/LJ5550**	6R1315	C9732A – Yellow	HP Color LaserJet 5500 Series, 5550 Series	12,000‡	12,000‡
LJ5500/LJ5550**	6R1316	C9733A – Magenta	HP Color LaserJet 5500 Series, 5550 Series	12,000‡	12,000‡
CP2025** 	6R1485	CC530A – Black	HP Color LaserJet CP2025 Series, CM2320 Series	3,500‡	3,500‡
CP2025** 	6R1486	CC531A – Cyan	HP Color LaserJet CP2025 Series, CM2320 Series	2,800‡	2,800‡
CP2025** 	6R1488	CC532A – Yellow	HP Color LaserJet CP2025 Series, CM2320 Series	2,800‡	2,800‡
CP2025** 	6R1487	CC533A – Magenta	HP Color LaserJet CP2025 Series, CM2320 Series	2,800‡	2,800‡

\*References Canon engine type. \*\*Contains a smart chip to enable smart print functions.

‡Yields declared in accordance with ISO/IEC 19752 Standard. †Yields declared in accordance with ISO/IEC 19798 standard.

# Color—HP Printer replacement toner supplies

Machine Type*	Xerox Part Number	Equivalent OEM Part Number	For Use In	OEM Stated Yield	Xerox Stated Yield
CP4005**	6R1326	CB400A – Black	HP Color Printer 4005 Series	7,500‡	7,500‡
CP4005**	6R1327	CB401A – Cyan	HP Color Printer 4005 Series	7,500‡	7,500‡
CP4005**	6R1328	CB402A – Yellow	HP Color Printer 4005 Series	7,500‡	7,500‡
CP4005**	6R1329	CB403A – Magenta	HP Color Printer 4005 Series	7,500‡	7,500‡
LJ4700**	6R1330	Q5950A – Black	HP Color LaserJet 4700 Series	11,000‡	11,000‡
LJ4700**	6R1331	Q5951A – Cyan	HP Color LaserJet 4700 Series	10,000‡	10,000‡
LJ4700**	6R1332	Q5952A – Yellow	HP Color LaserJet 4700 Series	10,000‡	10,000‡
LJ4700**	6R1333	Q5953A – Magenta	HP Color LaserJet 4700 Series	10,000‡	10,000‡
LJ3800/LJ3600 CP3505**	6R1338	Q6470A – Black	HP Color LaserJet 3800 Series, 3600 Series, Color Printer 3505 Series	6,000‡	6,000‡
LJ3600**	6R1339	Q6471A – Cyan	HP Color LaserJet 3600 Series	4,000‡	4,000‡
LJ3600**	6R1340	Q6472A – Yellow	HP Color LaserJet 3600 Series	4,000‡	4,000‡
LJ3600**	6R1341	Q6473A – Magenta	HP Color LaserJet 3600 Series	4,000‡	4,000‡
LJ3800/CP3505**	6R1343	Q7581A – Cyan	HP Color LaserJet 3800 Series, Color Printer 3505 Series	6,000‡	6,000‡
LJ3800/CP3505**	6R1344	Q7582A – Yellow	HP Color LaserJet 3800 Series, Color Printer 3505 Series	6,000‡	6,000‡
LJ3800/CP3505**	6R1345	Q7583A – Magenta	HP Color LaserJet 3800 Series, Color Printer 3505 Series	6,000‡	6,000‡
LJ2600/1600**	6R1410	Q6000A – Black	HP Color LaserJet 2600, 1600 Series, CM1015mfp, CM1017mfp	2,500‡	2,500‡
LJ2600/1600**	6R1411	Q6001A – Cyan	HP Color LaserJet 2600, 1600 Series, CM1015mfp, CM1017mfp	2,000‡	2,000‡
LJ2600/1600**	6R1413	Q6002A – Yellow	HP Color LaserJet 2600, 1600 Series, CM1015mfp, CM1017mfp	2,000‡	2,000‡
LJ2600/1600**	6R1412	Q6003A – Magenta	HP Color LaserJet 2600, 1600 Series, CM1015mfp, CM1017mfp	2,000‡	2,000‡
CP1215**	6R1439	CB540A – Black	HP Color LaserJet CP1201, 1215, 1510, 1515n, CM 1300, 1320 MFP	2,200‡	2,200‡
CP1215**	6R1440	CB541A – Cyan	HP Color LaserJet CP1201, 1215, 1510, 1515n, CM 1300, 1320 MFP	1,400‡	1,400‡
CP1215**	6R1441	CB542A – Yellow	HP Color LaserJet CP1201, 1215, 1510, 1515n, CM 1300, 1320 MFP	1,400‡	1,400‡
CP1215**	6R1442	CB543A – Magenta	HP Color LaserJet CP1201, 1215, 1510, 1515n, CM 1300, 1320 MFP	1,400‡	1,400‡

\*References Canon engine type. \*\*Contains a smart chip to enable smart print functions.

‡Yields declared in accordance with ISO/IEC 19752 Standard. †Yields declared in accordance with ISO/IEC 19798 standard.

# Black—HP, Apple Printer replacement toner supplies

Machine Type*	Xerox Part Number	Equivalent OEM Part Number	For Use In	OEM Stated Yield	Xerox Stated Yield
PX	6R899	HP92274A M2045GA	HP LaserJet 4L, 4ML, 4LC, 4P, 4MP, 4PJ, Apple Personal LaserWriter 300, 320	3,350‡	3,600‡
EX	6R903	HP92298A M2473G/A	HP LaserJet 4, 4+, 4M, 4M+, 5, 5M, 5N Apple LaserWriter 16/600, Pro 600, 630	6,800‡	7,300‡
EX Extended Yield	6R904	HP92298X M273G/A	HP LaserJet 4, 4+, 4M, 4M+, 5, 5M, 5N Apple LaserWriter 16/600, Pro 600, 630	8,800‡	9,800‡
VX	6R905	HPC3903A	HP LaserJet 5P, 5MP, 6P, 6MP	4,000‡	4,000‡
WX	6R906	HPC3909A	HP LaserJet 5si, 5siMX/NX, 5si Mopier, LaserJet 8000, HP240	15,000†	16,500‡
AX	6R908	HPC3906A	HP 5L, 6L, 3100, 3150	2,500†	2,500‡
62X	6R925	C4129X	HP LaserJet 5000, 5000N, 5000DN, 5000GN, 5100	10,000†	10,000‡
52X	6R926	HPC4127X	HP LaserJet 4000, 4000N, 4000T, 4000TN, 4050, 4050N, 4050T, 4050TN, 4050se	10,000†	10,000‡
22X	6R927	C4092A	HP LaserJet 1100, 1100se, 1100xi, 1100A, 1100A se, 1100A xi, 3200, 3200se	2,500†	2,500‡
32X	6R928	C4096A	HP LaserJet 2100, 2100M, 2100TN, 2100SE, 2100XI, 2200DN, 2200DSE, 2200DT, 2200DTN	5,000†	5,000‡
72X	6R929	C4182X	HP LaserJet 8100, 8100N, 8100DN, 8150, 8150N, 8150DN, 8150HN, 8150MFP	20,000†	20,000‡
LJ1200	6R932	C7115X	HP LaserJet 1000, 1200, 1200N, 1200se, 1220, 1220se, 3300MFP, 3310, 3320MFP, 3320NMFP, 3330MFP	3,500†	3,500‡
LJ4100	6R933	C8061X	HP LaserJet 4100, 4100N, 4100TN, 4100DTN, 4100MFP, 4101MFP	10,000†	10,000‡
LJ1150	6R956	Q2624X	HP LaserJet 1150	4,000†	4,000‡

\*References Canon engine type. \*\*Contains a smart chip to enable smart print functions.

†Yields declared in accordance with ISO/IEC 19752 Standard. ‡Yields based on 5% toner area coverage.

# Black—HP, Apple Printer replacement toner supplies

Machine Type*	Xerox Part Number	Equivalent OEM Part Number	For Use In	OEM Stated Yield	Xerox Stated Yield
LJ1300	6R957	Q2613X	HP LaserJet 1300, 1300n	4,000†	4,000‡
LJ4200**	6R934	Q1338A	HP LaserJet 4200, 4200n, 4200tn, 4200dtn, 4200dtns, 4200dtnsl	12,000‡	13,200†
LJ4300/LJ4345mfp**	6R935	Q1339A Q5945A	HP LaserJet 4300, 4300n, 4300tn, 4300dtn, 4300dtns, 4300dtnsl, HP LaserJet 4345mfp, 4345x mfp, 4345xm mfp, 4345xs mfp	18,000‡	19,800†
LJ2300**	6R936	Q2610A	HP LaserJet 2300, 2300d, 2300n, 2300dn, 2300dtn	6,000†	6,600†
LJ9000**	6R958	C8543X	HP LaserJet 9000, 9000n, 9000dn, 9000hns, 9000mfp, 9040mfp, 9050, 9050dn, 9050mfp	30,000†	33,000†
LJ4250/LJ4350**	6R959	Q5942X	HP LaserJet 4250, 4250n, 4250tn, 4250dtn, 4250dtnsl HP LaserJet 4350, 4350n, 4350tn, 4350dtn, 4350dtnsl	20,000†	22,000†
LJ2400**	6R961	Q6511X	HP LaserJet 2410, 2420, 2420d, 2420dn, 2430, 2430dtn, 2430n, 2430t, 2430tn	12,000†	12,000†
LJ1160/LJ1320/ LJ3390**	6R960	Q5949A	HP LaserJet 1160, 1320 Series, 3390 Series	2,500†	3,500†
LJ1320/LJ3390**	6R1320	Q5949X	HP LaserJet 1320 Series, 3390 Series	6,000†	6,000†
LJP2015/LJM2727mfp**	6R1387	Q7553X	HP LaserJet P2015 Series, M2727mfp	7,000†	7,000†
LJP3005/LJM3027mfp/ LJM3035mfp**	6R1388	Q7551X	HP LaserJet P3005 Series, M3027mfp, M3035mfp	13,000†	13,000†
LJ5200**	6R1389	Q7516A	HP LaserJet 5200 Series	12,000†	12,000†
LJ1010	6R1414	Q2612A	HP LaserJet 1010, 1012, 1015, 1018, 1020, 1022 Series, 3015, 3030 Series, 3050, 3052, 3055, M1319f mfp	2,000†	2,000†
LJ1006**	6R1429	CB435A	HP LaserJet P1005, P1006	1,500†	1,500†
LJ1505**	6R1430	CB436A	HP LaserJet P1505, P1505n, M1522n, M1522nf	2,000†	2,000†
P2035/P2055** Available April	6R1489	CE505A	HP LaserJet P2035 Series, P2055 Series	2,300‡	2,300‡
P2055** Available April	6R1490	CE505X	HP LaserJet P2055 Series	6,500‡	6,500‡
P4015**	6R1443	CC364A	HP LaserJet P4014n, 4015 Series, 4515 Series	10,000†	10,000†

\*References Canon engine type. \*\*Contains a smart chip to enable smart print functions.

†Yields declared in accordance with ISO/IEC 19752 Standard. ‡Yields based on 5% toner area coverage.

# Brother Laser Printer replacement toner and drum cartridges

Machine Type	Xerox Part Number	Equivalent OEM Part Number	For Use In	OEM Stated Yield	Xerox Stated Yield
HL-2040	6R1415	TN350	Fax-2820/Fax-2910/Fax-2920/HL-2040/	2,500	2,500
	6R1416	DR350	HL-2070N/DCP-7020/MFC-7220/MFC-7225N/ MFC-7420/MFC-7820N	12,500	12,500
HL-5250	6R1417	TN550	DCP-8060/DCP-8065/DCP-8065DN/HL-5240/	3,500	3,500
	6R1418	TN580	HL-5250DN/HL-5250DNT/HL-5280DW/MFC-8460N/	7,000	7,000
	6R1419	DR520	MFC-8660DN/MFC-8670/MFC-8860DN/MFC-8870DW	25,000	25,000
HL-1240	6R1420	TN430	DCP-1200/DCP-1400/Fax-4100/Fax-4100e/Fax-4750/	3,000	3,000
	6R1421	TN460	Fax-4750e/Fax-5750/Fax-5750e/HL-1200/HL-1230/	6,000	6,000
	6R1422	DR400	HL-1240/HL-1250/HL-1270/HL-1435/HL-1440/	20,000	20,000
			HL-1450/HL-1470N/MFC-1260/MFC-8300/MFC-8500/MFC-8600/MFC-8700/MFC-9600/MFC-9700/MFC-9800		
HL-5140	6R1423	TN540	DCP-8040/DCP-8045D/HL-5100/HL-5140/HL-5150/	3,500	3,500
	6R1424	TN570	HL-5150D/HL-5150DLT/HL-5170DN/HL-5170DNLT/	6,700	6,700
	6R1425	DR510	MFC-8120/MFC-8220/MFC-8440/MFC-8640D/	20,000	20,000
			MFC-8840/MFC-8840D/MFC-8840DN		

# Replacement cartridges

## Good for performance and conservation.

Our replacement cartridges keep plastic out of the waste stream. While they contain new and reprocessed components, all critical xerographic components are 100% new. Our cartridges feature Xerox specified and approved toner, as well as new photoreceptors, cleaning blades, certified developer roll sleeves and more.

## Triple tested for quality assurance.

Our Xerox Replacement Cartridges are triple tested for manufacturing quality. We perform life testing in our labs to ensure that cartridges are meeting our quality specs from first print to last. Then, every cartridge is print tested before packaging. Periodic, random cartridge audits ensure consistent quality each and every time.

## 100% risk-free warranty.

Each replacement cartridge is backed by the Xerox Total Performance Warranty. If you're not satisfied, we're not satisfied. Experience real value that works for you.



**For warranty questions in North America call:  
1-866-XEROX-4U**



©2010 Xerox Corporation. All rights reserved. XEROX® and XEROX and design® are trademarks of Xerox Corporation in the United States and/or other countries. "HP" is a registered trademark of Hewlett-Packard. BROTHER is a registered trademark of Brother Industries, Ltd. Japan in the U.S. and many other countries. 03/10

701P48535